

FILE REVIEW CHECKLIST

◀ SITE DATA ▶

Site Name: BILLIKENS TV CENTER		Street: 12515 PACIFIC HWY SW	
City: TALOMA	State: WASH	Zip: 98499	County: PIERCE
EPA ID No: WAD0600053121		SIC:	Site area(acres):
Latitude: / /	Longitude: / /	Section:	Township: Range:
Hazard Ranking Score (HRS):		HRS Date:	

◀ SITE ACTIVITY ▶

<input type="checkbox"/>	Generator	<input type="checkbox"/>	Abandoned Site	<input type="checkbox"/>	Treatment-Storage-Disposal
<input type="checkbox"/>	Transporter	<input type="checkbox"/>	Spill	<input type="checkbox"/>	Other:

◀ FILE REVIEW SUMMARY ▶

Recommendation:	<input checked="" type="checkbox"/> A1	Close File	<input type="checkbox"/>	Further Review	<input type="checkbox"/>	Other:
	<input type="checkbox"/>	Score Site	<input type="checkbox"/>	Site Visit	<input type="checkbox"/>	

Comments:

THIS IS A TV REPAIR SHOP WHICH IS NEAR LAKERDOD WATER DISTRICTS CONTAMINATED WELLS. A DOE SITE VISIT SHOWED THAT NO SOLVENTS ARE USED AND NO PROBLEM EXISTED.

USEPA SF



1568515

Reviewer: ANDREW THOMAS E+E INC.

Date: 3/30/83

HAZARDOUS WASTE INFORMATION

General Type		Source of Waste	
Organics		Mining	Transformers
Inorganics		Construction	Utility Companies
Solvents		Textiles	Sanitary/Refuse
Pesticides		Fertilizer	Photofinish
Heavy Metals		Paper/Printing	Lab/Hospital
Acids		Leather Tanning	Unknown
Bases		Iron/Steel Foundry	Other:
PCB		Chemical, General	TV REPAIR
Municipal Waste		Plating/Polishing	
Unknown		Military/Ammunition	
Other:		Electrical Conductors	

Period of disposal, from:

to;

Material	Toxicity	Persistence	Physical State	Quantity (1)	Facility Type (2)	Containment (3)

(1) gallons-cubic yards-tons.

(3) none-leaking-good-unknown

(2) piles-land treatment-landfill-tanks-impoundment-underground injection-drums,above ground-drums,below ground-other

◀ POTENTIAL HAZARD RANKING SYSTEM SCORE ▶

Groundwater/Surface Water Route										Air Route																													
Hazardous Waste Quantity: 0 1 2 3 4 5 6 7 8												Waste Characteristics:																											
												Reactivity/Incompatibility 0 1 2 3																											
												Toxicity 0 1 2 3 (X3)																											
												Hazardous Waste Quantity 0 1 2 3 4 5 6 7 8																											
Toxicity/Persistence 0 3 6 9 12 15 18																																							
Potential Score										/26 X 100=										Potential Score										/20 X 100=									

◀ EVENTS ▶

Event	Date Started	Date Completed	Conducted By				Count
			EPA	State	Resp. Party	Other	
Site Discovery		8/1/18					
Preliminary Assessment		/					
Site Investigation	8/1/18	8/1/18		X			
Remedial Action	/	/					
Removal Action	/	/					
Enforcement Investiga.	/	/					
Administrative Order	/	/					
Judicial Action	/	/					

◀ DATA/INFORMATION AVAILABLE IN FILE ▶

Type of Data/Information	Yes	No	Attached
Groundwater Analyses		X	
Surface Water Analyses		X	
Air Quality Analyses		X	
Location Map		X	
Site Plan		X	
Well Logs		X	
Soil Type		X	

Additional comments and information: